

PUMP CASING INTERNAL REPAIR

ID: 9049



PROBLEM

Customer had small through wall pin holes in the internals of a pump. Customer was facing a six month time before a new manufactured pump internal could be made and put into service. The issue may have been caused by corrosion or cavitation.

APPLICATION SITUATION

Belzona Houston was able to be onsite to look at the casing on the same day as receiving the call. This allowed us to complete a repair plan and have the casing picked up the next day, and brought to our shop for repair. Within three days, that's including delivery time, we were able to patch the holes and seal the internals of the casing. This was a significant benefit for the customer who needed this asset back in service as soon as possible.

The casing was 11" diameter.

Three small 1/8" size through wall holes.

Max operating temp = 320 deg F

Max pressure = 133 psi

APPLICATION METHOD

1. We picked up the pump casing onsite of customer and brought it to our shop.
2. We complete surface preparation via vapor blasting, with emerald grit.
3. We patched the through wall defects by using Belzona 1511 and Belzona 9341 reinforcing mesh.
4. We applied a two coat system of Belzona 1593.

BELZONA FACTS

Quick turnaround to get this asset back in service saved customer down time, and significant amount of money.

An effective solution to get this asset back in service provided the customer time to order a new casing to replace in a timely cost efficient manner.

Relatively inexpensive cost compared to replacing.

INDUSTRY

Chemical & Petrochemical

LOCATION

Pasadena, TX, USA

APPLICATION DATE

March 2023

PRODUCTS

Belzona 1511 (Super HT-Metal)

Belzona 1593

Belzona 9111 (Cleaner Degreaser)

SUBSTRATE

Carbon steel

PHOTOS

1. Pump internals after it was abrasive blasted. Two small holes shown.
2. Pump internals were coated with Belzona 1593.
3. Close up on patched area with coating over top.
4. Back side view of completed project.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

BELZONA®