

BELZONA BONDS PIPE SUPPORTS ON TOP OF A CHEMICAL TANK ROOF.

ID: 9067



PROBLEM

Installation of five 12"x12" pipe supports on top of a newly rubber-lined Sulphuric Acid (H₂SO₄) tank.

APPLICATION SITUATION

Pipe supports on top of a Chemical Storage Tank within a Petrochemical facility.

APPLICATION METHOD

The five support areas were ground to SSPC-SP11 cleanliness and a 75 microns profile, prior to the Belzona 7311 being applied at the recommended 2mm thickness onto the tank roof and pipe support. The application was carried out in accordance with Belzona System Leaflet TCC-06.

BELZONA FACTS

Welding was not an option as it would have burned the internal tank lining. The Customer was very impressed with the ease of application and performance of Belzona 7311, successfully winning the Distributor a couple more pipe support bonding applications.

INDUSTRY

Chemical & Petrochemical

LOCATION

Alabama

APPLICATION DATE

May 2022

PRODUCTS

Belzona 7311

SUBSTRATE

Carbon steel

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.