

BELZONA TANK BASE SEALING SEALS OUT THE WEATHER

ID: 9072



PROBLEM

The areas round the base of the tanks were deteriorating and required protection from the elements, to prevent moisture ingress under the tanks.

APPLICATION SITUATION

Belzona offered a fast turnaround for the tanks in the timeframe required by the operator, offering future protection of the tanks.

APPLICATION METHOD

Belzona 3211 was applied as per system leaflet GSS-03.

BELZONA FACTS

Belzona offered a solution allowing for moisture ingress to be mitigated, helping reduce any future metal loss of the tank base.

INDUSTRY

Chemical & Petrochemical

LOCATION

Spain

APPLICATION DATE

January 2023

PRODUCTS

Belzona 3211 (Lagseal)

Belzona 3921 (GSC Surface Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Photo of a tank prior to application.
2. Photo of a tank prior to application.
3. Application in progress.
4. One of the tanks with the tank base sealing system installed.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

