

BELZONA REPAIRS OVERHEAD CONCRETE ABOVE PEDESTRIAN WALKWAY AT LOCAL HOSPITAL

ID: 9088



PROBLEM

Pieces of Concrete were falling from bottom of sidewalk ramp 10 ft above pedestrian walkway

APPLICATION SITUATION

We got the job because of the material and time savings. Belzona 4141 applied upside down and fast cure time. This limited the down time in the area from the walkway having to be closed for a long time. They needed the job done quick , quiet and easy.

APPLICATION METHOD

We set up safe zone and barricaded to keep pedestrians from trafficking into the work area. Plastic was put down under repair areas. We chiseled out repair areas and removed rust from any exposed rebar. We applied Belzona 4911 Conditioner first then the Belzona 4141 Concrete repair material. It was quite difficult hanging the Belzona 4141 upside down but we persevered. Would probably use some plyboards next tiime.

BELZONA FACTS

Really not many other options to repair these due to location and the need to cure fast. We have many more such areas to repair.

INDUSTRY

Buildings & Structures

LOCATION

Greensboro, North Carolina

APPLICATION DATE

May 2023

PRODUCTS

Belzona 4141FR

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

