

BELZONA RESTORES KITCHEN WASHROOM FLOOR

ID: 909



PROBLEM

The terrazzo floor had degraded from constant cleaning and contact with cleaning solutions.

APPLICATION SITUATION

Hospital kitchen washroom floor

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. Belzona® 5231 was applied and extra grit broadcast on top.

BELZONA FACTS

A competitive bid was placed for the removal of existing surface and new terrazzo floor applied. Belzona was faster, cleaner, and less expensive than the other process.

INDUSTRY

General Industry

LOCATION

Hospital - Albuquerque, New Mexico, USA

APPLICATION DATE

October 2007

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 5231 (SG Laminate)

SUBSTRATE

Terrazzo

PHOTOS

1. Close-up of original damaged floor
2. Heavy damage in washdown room
3. Finished floor where washing machine goes
4. Finished floor from outside hallway

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

