

BELZONA PROTECTS CONTAINMENT AREA

ID: 914



PROBLEM

The previous coating had failed causing significant damage to the underlying concrete.

APPLICATION SITUATION

Containment area for water treatment chemicals.

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflets TCC-9 & 15

BELZONA FACTS

Previous attempts to coat this area had failed due to the chemical concentration. Belzona was chosen for its high chemical resistance. The two color system was also seen as an advantage as it will show when the coating needs to be touched up.

INDUSTRY

Power

LOCATION

Power Project - Bastrop, Texas, USA

APPLICATION DATE

November 2007

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 4311 (Magma CR1)

SUBSTRATE

Concrete

PHOTOS

1. Containment area prior to being coated
2. Area prepared and leveled with Belzona 4111
3. First coat of Belzona 4311 being applied
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

