

COOLING WATER PUMP PROTECTION

ID: 9154



PROBLEM

The customer performed a plant shutdown and within the schedule was the preventive maintenance of the pump in which damage to the internal coating was evidenced and they decided to replace it.

APPLICATION SITUATION

This cost-effective coating performs well in erosive environments.

APPLICATION METHOD

It was protected with Belzona 5821 based on the CEP-3 know how system.

BELZONA FACTS

The customer chose Belzona because of its market recognition of its ability to extend equipment life.

INDUSTRY

Chemical & Petrochemical

LOCATION

Cartagena/Colombia

APPLICATION DATE

December 2017

PRODUCTS

Belzona 5821

SUBSTRATE

Carbon steel

PHOTOS

1. Complete view of the pump.
2. First beige layer.
3. Second gray layer.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

