

BUTTERFLY VALVE REBUILDING

ID: 9157



PROBLEM

The sealing rubber was broken, which causes water to come into direct contact, eroding the substrate where the seal is made.

APPLICATION SITUATION

The customer was happy with quick turnaround.

APPLICATION METHOD

To maintain the original dimensions, it was necessary to cut some neoprene strips and cable glands to use them as molds to apply BELZONA 1111.

BELZONA FACTS

A quick and localized repair was performed with Belzona putting the equipment back into service as soon as possible.

INDUSTRY

Chemical & Petrochemical

LOCATION

Barranquilla, Colombia

APPLICATION DATE

March 2018

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 9411 (Release Agent)

SUBSTRATE

Carbon steel

PHOTOS

1. View of valve damage.
2. Demolding of neoprene strips
3. Final finishing.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

