

INTERNAL FLOATING ROOF (IFR) REPAIR - BELZONA FLORIDA

ID: 9177



PROBLEM

Customer needed to repair their IFR (Internal Floating Roof) cable guides because corrosion issues we're chronic and an easy repair needed to be found.

APPLICATION SITUATION

They needed an adhesive that they could trust to bond the new aluminum pieces in place. Belzona 1121 was chosen for its outstanding performance characteristics, ease of use and extended working life

APPLICATION METHOD

Standard surface preparation through the use of an angle grinder and a carbide grinding wheel.

BELZONA FACTS

Belzona 1121 allowed the customer to replace nearly 40 units and just a few hours.

INDUSTRY

General Industry

LOCATION

Port Canaveral, Florida

APPLICATION DATE

November 2023

PRODUCTS

Belzona 1121 (Super XL-Metal)

SUBSTRATE

Aluminum

PHOTOS

1. Area being prepped.
2. 1121 product being mixed.
3. 1121 being applied to the piece that will be bonded.
4. Finished application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

