

BELZONA REPAIRS AND SEALS IRON GUTTER

ID: 918



PROBLEM

The cast iron had over time corroded and the joints deteriorated allowing water to enter the internal fabric of the building.

APPLICATION SITUATION

Traditional cast iron gutter 0.5 meters wide by 64 meters long

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6.

BELZONA FACTS

The cost of the Belzona was a fraction of the replacement cost of the cast iron gutter which was the other alternative.

INDUSTRY

Buildings & Structures

LOCATION

Logistics Factory, Lancashire - UK

APPLICATION DATE

April 2007

PRODUCTS

Belzona 3111 (Flexible Membrane)
Belzona 3921 (GSC Conditioner)
Belzona 9311 (Reinforcing Sheet)

SUBSTRATE

Cast Iron

PHOTOS

1. Blocked and corroded gutter
2. Gutter drained ready for preparation
3. Belzona fully reinforced Flexible Membrane system
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

