


BELZONA QUICKLY COATS AND PROTECTS ASPHALT SHINGLE COLOR PROCESS CONE/SILO

ID: 9204



PROBLEM

Old Silo had expired with countless holes. Addressed with makeshift patches, emitting product into the air. The customer was looking for a long term abrasion resistant solution.

APPLICATION SITUATION

Customer was looking for a long term solution for a brand new silo cone. The old cone had endured countless damages due to abrasion/erosion. Belzona was critical due to limited time frame during a plant shutdown.

APPLICATION METHOD

Blasting took one day, and coating/application of Belzona 1321 (Ceramic S-Metal), bonding the Belzona 9811 Alumina Tiles, and grouting with 1814/1813 over the next two days resulting in a three day application process. The Cone is 255 sq ft. It was installed during a plant shutdown days later.

BELZONA FACTS

Fast cure times resulted in convenient application during a critical limited timeframe of a costly plant shut down.

INDUSTRY

Mining & Quarrying

LOCATION

Norwood, MA

APPLICATION DATE

November 2023

PRODUCTS

Belzona 1321 (Ceramic S-Metal)
Belzona 1813
Belzona 1814
Belzona 9811

SUBSTRATE

Stainless-steel

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

