


BELZONA REPAIRS CONVEYOR BELT

ID: 9213



PROBLEM

A 10 meter section of the top layer rubber on a belt wore out.

APPLICATION SITUATION

The client needed a fast solution to assist them until the next outage.

APPLICATION METHOD

After abrading the belt, it was cleaned and degreased with Belzona 9111. A thin layer of Belzona 2911 Conditioner was applied to the damaged section.

Once the conditioner was touch dry, Belzona 2131 was applied and allowed to fully cure.

BELZONA FACTS

Instead of shutting the entire section down to replace the belt, Belzona saved the client time and money.

INDUSTRY

Mining & Quarrying

LOCATION

Botswana

APPLICATION DATE

August 2015

PRODUCTS

Belzona 2131 (D & A Fluid Elastomer)
Belzona 2911 (Elastomer QD Conditioner)
Belzona 9111 (Cleaner Degreaser)

SUBSTRATE

Rubber

PHOTOS

1. Condition of belt
2. After application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

