

WEATHERPROOFING ROOF RIDGE CAP

ID: 9248



PROBLEM

In the pictures below you will see a fiberglass housing unit for power supply in a local chemical plant. These units each have an aluminum ridge cap on the roof that comes from the manufacturer siliconed to the fiberglass panel. During transportation they become loose due to the flexibility of the fiberglass and from just being in the weather constantly the silicone deteriorates causing a leaking hazard inside the unit. This can and has caused major power outages inside the plant.

APPLICATION SITUATION

This application stemmed from a previous weatherproofing application we performed on rubber zipper boots. This caused a major power outage to over half of the plants power supply causing a 4 hour shutdown and costing roughly over \$3,000,000.00 in lost revenue. Our application of Belzona 3121 and reinforcement cloth only took two hours to complete and caused the plant zero downtime.

APPLICATION METHOD

1st step: we removed any loose silicone then prepped the fiberglass and aluminum cap with a Metabo bristle blaster.

2nd step: we then cleaned the areas with Belzona degreaser and wiped clean. Taped off each side for a perfect straight line. Then applied our first coat of Belzona Belzona 3121.

3rd step: we wet out our Belzona reinforcement cloth using Belzona 3121 and applied it to the areas that we have prepped. Once all areas have the first coat and reinforcement cloth down and no wrinkles showing we move to the final step.

4th and final step: is to completely saturate the cloth with a second coat of Belzona 3121 making sure to coat thoroughly to properly cover the reinforcement cloth. Remove tape and Clean up!

BELZONA FACTS

Cost saving compared to a replacement roof cap was around \$5000.00. The customer has used Belzona in many of the other areas in the plant and they believe in and trust Belzona.

INDUSTRY

Chemical & Petrochemical

LOCATION

Decatur, Alabama

APPLICATION DATE

October 2023

PRODUCTS

Belzona 3121 (MR7)

Belzona 9111 (Cleaner Degreaser)

SUBSTRATE

Aluminum

PHOTOS

1. Rectifier Housing
2. Aluminum ridge cap coated with Belzona 3121
3. Final application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

