

BELZONA COLD BONDS HOLED STEAM PIPE

ID: 9250



PROBLEM

The client in the Steel industry suffered a through wall hole in their steam pipeline.

APPLICATION SITUATION

The client chose Belzona due to being able to carry out the maintenance without the need for hot work. A pre-fabricated metal plate was created to cover the defect area and bonded with Belzona 1511 a high temperature paste grade material to adhere the plate to the metal pipe.

APPLICATION METHOD

Repaired in accordance with VPF-11 • FOR REPAIRING LEAKS IN PIPES

BELZONA FACTS

Belzona was selected due to being able to carry out the application in situ.

INDUSTRY

Steel & Metal Processing

LOCATION

Netherlands

APPLICATION DATE

July 2020

PRODUCTS

Belzona 1511 (Super HT-Metal)
Belzona 5892

SUBSTRATE

Carbon steel

PHOTOS

1. Defect in the pipe
2. Plate bonded on with Belzona 1511
3. Complete application overcoated with Belzona 5892

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

