


FOOD MANUFACTURING FACILITY HAS BELZONA REPAIR END QUOTE REFRIGERATOR FLOOR

ID: 9270



PROBLEM

The floor in this refrigerator has been sitting on sub zero temperatures for 25 years. Constant freezing and unfreezing has left the concrete floor in very bad condition. In some areas it had up to two inches of concrete loss.

APPLICATION SITUATION

The only down time the customer had was over a long weekend. This floor was not suitable for food refrigeration and had to be taken care of as soon as possible. The preparation cleaning resurfacing and coating of this floor was done in three days. The customer is extremely happy with the outcome of the floor and has three more refrigeration units to be done shortly with Barzona repair system.

APPLICATION METHOD

The Belzona products were applied by hand

BELZONA FACTS

Belzona is the only coating supplier that is trusted by this food facility. Over the last few years multiple repairs has been done to this facility using only Belzona products.

INDUSTRY

Food & Drink

LOCATION

Oklahoma City, Oklahoma

APPLICATION DATE

February 2024

PRODUCTS

Belzona 4154 (Bulkfill Resin)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. Area prior to application
2. Commencement of application
3. Belzona 5811 applied to area
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

