

BELZONA COATS STACK WHILST IN SERVICE

ID: 929



PROBLEM

External corrosion protection required but stack could not be taken out of service.

APPLICATION SITUATION

Vent stack for hot gases operating between 300 & 550°F (150 & 280°C) internal temperature.

APPLICATION METHOD

Brush applied with a 4" bristle brush by hand.

BELZONA FACTS

Coating was less expensive than any other alternative considered by customer. It also allowed application without taking chimney out of service saving more time and money. Belzona® 5851 also required no surface preparation saving more time and money.

INDUSTRY

General Industry

LOCATION

North American Galvanizing

APPLICATION DATE

July, 2007

PRODUCTS

Belzona 5851 (HA-Barrier)

SUBSTRATE

Steel

PHOTOS

1. Original chimney
2. Test strip - top portion, bottom - burned portion
3. Final application - 4 months later

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

