

BELZONA ENERGY-SAVING COATINGS IMPROVE PUMP EFFICIENCY

ID: 9312



PROBLEM

The pump efficiency test of the customer's new pump found that the target value was not reached.

APPLICATION SITUATION

The circulating water pump applies Belzona energy-saving and efficiency-enhancing coating.

APPLICATION METHOD

Application was carried out in accordance with Belzona System leaflet CEP-10.

BELZONA FACTS

The pump efficiency of the new pump was tested before leaving the factory and it was found that it did not reach the target value. Traditional methods of smoothing the substrate surface to reduce fluid resistance and enhance pump efficiency have had limited success. The customer chose to apply Belzona energy-saving and efficiency-enhancing coating to the overall internal flow surface of the pump casing, and the pump efficiency was improved. The effect is significant. The test of pump efficiency before and after the coating applied showed that pump efficiency increased by more than 3%, far exceeding the pump efficiency target value required for delivery and far exceeding customer expectations.

INDUSTRY

Fluid Flow

LOCATION

Jiangsu, China

APPLICATION DATE

May 2019

PRODUCTS

Belzona 1341 (Supermetalgilde)

SUBSTRATE

Cast Iron

PHOTOS

1. Before application
2. After surface preparation
3. During application of Belzona 1341
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

