

BELZONA SUPERWRAP II REPAIRS AND STRENGTHENS ASH CHUTES

ID: 9325



PROBLEM

The customer burns non-recyclables and re-use the energy from the combustion. The ash left from burning comes down the chutes wearing holes due to sliding abrasion specifically on the elbows and joints where the ash has more contact.

APPLICATION SITUATION

All the chutes are very thin and near impossible to weld where holes had appeared so the customer liked the idea of 1983 SuperWrap II which would repair and seal the holes. It would also provide strength to the thin through wall and give some wall strength to the worn away sections.

APPLICATION METHOD

The substrate was bristle blasted to provide the required substrate key profile. The termination points were taped out and Belzona 1983 SuperWrap II was applied 50/50 to increase strength to specified standard. A consolidator sheet was applied until application had cured to IFU specification.

BELZONA FACTS

The customer was delighted with the solution and is having all the chutes replaced in a June shutdown with Belzona SuperWrap II applied to give the new chutes some strength and longer durability.

INDUSTRY

Other

LOCATION

Bristol

APPLICATION DATE

March 2024

PRODUCTS

Belzona 1983 (SuperWrap II)

SUBSTRATE

Other

PHOTOS

1. Ash chute had worn due to sliding abrasion
2. Damaged area was bristle blasted to key profile
3. Belzona 1983 SuperWrap II is applied then Belzona 9382 release film is applied to consolidate application
4. Release film is removed and repair application is complete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

