

# REFURBISHMENT AND PROTECTION OF WATER-POLYMER MIXTURE TANK FROM FURTHER CORROSION

ID: 9338



## PROBLEM

Tank was very badly corroded and required refurbishment and protection

## APPLICATION SITUATION

Customer needed to protect tank from further deterioration and against corrosion due to the immersion in a mixture of water and polymer.

## APPLICATION METHOD

All the elbows were grit blasted to SSPC SP10 and two coats of Belzona 5811 were applied.

## BELZONA FACTS

Customer was happy with the ease of mixing and applying Belzona 5811.

## INDUSTRY

Water / Wastewater

## LOCATION

Ontario, Canada

## APPLICATION DATE

August 2023

## PRODUCTS

Belzona 5811 (Immersion Grade)

## SUBSTRATE

Carbon steel

## PHOTOS

1. Tank exterior prior to application.
2. Tank interior prior to application.
3. After sand blasting and application of two coats of Belzona 5811

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](https://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](https://www.belzona.com)

