

BELZONA SEALS WAREHOUSE FLOOR

ID: 934



PROBLEM

Chemical spills however quickly cleaned up could contaminate ground-water. Facility near two major rivers. Floor had many cracks and gaps around wall to floor detail.

APPLICATION SITUATION

Major Industrial gas/chemical producer has warehouse full of 55 gallon drums, with no containment for spills.

APPLICATION METHOD

Application was carried out following Belzona Know-How System Leaflets FPA-6 and TCC-15. Cracks were chased out before being filled and sealed.

BELZONA FACTS

Customer satisfied with other work at facility and inspection in March 2007 showed all Belzona to be in perfect condition.

INDUSTRY

Buildings & Structures

LOCATION

Chemical Producer, Pennsylvania USA

APPLICATION DATE

February 2004

PRODUCTS

Belzona 4131 (Magma Screed)
Belzona 4251 (Magma Flex Fluid)
Belzona 3121 (MR-7)

SUBSTRATE

Concrete floor with block walls

PHOTOS

1. Floor to wall joint before sealing
2. Sealing warehouse floor-expansion joints
3. Sealing joint around perimeter
4. Repaired/sealed cracks with Belzona 4131

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

