

WEAKENED PIPE REINFORCED WITH PLATE BONDING AND SW

ID: 9342



PROBLEM

A pipe in a wastewater plant needed had suffered from external corrosion and metal loss over the years.

APPLICATION SITUATION

The pipe was so deteriorated that they were concerned that abrasive blasting the bottom of the pipe will puncture the pipe and create through wall defects. It was decided to do a plate bonding with a surface tolerant product as an initial reinforcement before further reinforcing with SWII.

APPLICATION METHOD

First, the pipe was prepared as best as possible. The we did a plate bonding repair with Belzona 1161 to protect the bottom section of the pipe. After, we grit blasted the rest of the pipe and reinforced the rest of the pipe with Belzona Superwrap II.

BELZONA FACTS

The pipe was so deteriorated that it was about to have through wall defects and they could not shutdown operations. The Belzona solution presented minimal disruption to their operations and they were able to reinforce and protect the pipe for many years.

INDUSTRY

Water / Wastewater

LOCATION

Ontario, Canada

APPLICATION DATE

May 2021

PRODUCTS

Belzona 1161 (Super UW-Metal)
Belzona 1982 (SuperWrap II)
Belzona SuperWrap

SUBSTRATE

Carbon steel

PHOTOS

1. Defective pipe
2. Plate bonding over the most critical area
3. 1st layer of Belzona SWII
4. Complete repair after consolidating with the release film to be later removed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

