

# REVIVING GRAY AND BLACK TANKS INSIDE A MARINE VESSEL WITH BELZONA SOLUTIONS

ID: 9343



## PROBLEM

The gray and black tanks inside the marine vessel were suffering from coating failure and corrosion issues. The main flange also required repair from wear.

## APPLICATION SITUATION

The gray and black tanks inside a marine vessel were suffering from coating failure and corrosion issues and the main flange from wear.

## APPLICATION METHOD

After solvent cleaning, and then with the use of a power tool, tank internal surfaces were prepared to SP11. Flanges were also rebuilt using Belzona 1111. Two coats of Belzona 5811 were then applied.

## BELZONA FACTS

Adequate technical support was given to ensure application was carried out according to standards.

## INDUSTRY

Marine

## LOCATION

Ontario, Canada

## APPLICATION DATE

September 2023

## PRODUCTS

Belzona 1111 (Super Metal)

Belzona 5811 (Immersion Grade)

## SUBSTRATE

Cast Iron

## PHOTOS

1. Tanks before surface preparation.
2. After surface preparation.
3. Gray Tank After application of two coats of Belzona 5811.
4. Black Tank After application of two coats of Belzona 5811.

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](https://www.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](https://www.belzona.com)

