

BELZONA REBUILDS SEAL FACE ON RAW MILL AT CEMENT PLANT

ID: 935



PROBLEM

Abrasion from the felt seal and limestone wore this major component of the mill.

APPLICATION SITUATION

Rotating table of grinding mill for raw materials used in the production of cement.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-13. Limited access only allowed hand grinding for preparation followed by application of the Belzona® 1812 by trowel.

BELZONA FACTS

Replacement was not an option and due to heat stress welding could not be attempted. Past success with Belzona in the plant led to its use, saving millions of dollars in potential production losses.

INDUSTRY

Cement

LOCATION

Cement Plant, Nazareth, Pennsylvania

APPLICATION DATE

March, 2007

PRODUCTS

Belzona 1812 (Ceramic Carbide FP)

SUBSTRATE

Steel

PHOTOS

1. Raw mill overall size
2. Worn seal area on rotating table
3. Belzona 1812 applied and new felt seal and holder installed
4. Another general view of the mill

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

