


BELZONA SMOOTHS OUT COMPETITION

ID: 9350



PROBLEM

The expansion joint had been damaged and breaking up grout from North to the west end surgical area.

APPLICATION SITUATION

The other way they were being addressed was creating a big hump in the walkway and we could be smooth. Also we could be out in two days.

APPLICATION METHOD

Removed old expansion joint and chipped out grout around area. Grinded down concrete to make a smooth transition. Built up concrete with Belzona 4111, created expansion joint with Belzona 2221 and coated transition with Belzona 5231

BELZONA FACTS

Belzona saved the customer several complaint's with hump's in expansion joints and no more getting x ray machines hung up on floor.

INDUSTRY

Buildings & Structures

LOCATION

Lafayette

APPLICATION DATE

February 2024

PRODUCTS

Belzona 2221 (MP Fluid Elastomer)
Belzona 4111 (Magma-Quartz)
Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

1. Removing existing expansion joint
2. After grout was removed
3. Finished smooth ride
4. completed smooth ride application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

