

BELZONA REFURBISHES LABORATORY WORKTOPS

ID: 937



PROBLEM

Severely degraded counter tops needed to be resurfaced with a chemically resistant coating.

APPLICATION SITUATION

State Health Dept was building new facility and needed to extend life of existing facility lab counter tops

APPLICATION METHOD

Application carried out in accordance with modified Belzona System leaflet FPA-3. Special care was taken to clean sand the surfaces. Belzona® 5811 applied over-thickness with a trowel to create a self levelling coat.

BELZONA FACTS

Saved tens of thousands of dollars on replacements. In December 2007 Facilities Manager reports all is well, no complaints from workers.

INDUSTRY

Water / Wastewater

LOCATION

State Health Dept.

APPLICATION DATE

March 2005

PRODUCTS

Belzona 5811 (Immersion Grade)

SUBSTRATE

unknown

PHOTOS

1. Sink in lab before work
2. Fume cupboard before work
3. Sink after coating
4. Counter top after coating

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

