

BELZONA SUPER WRAP ON A CONCRETE STAND FOR A PIPE AT A POWER STATION

ID: 9377



PROBLEM

The concrete pedestal holding up a pipe formed a crack over the years of exposure to the elements.

APPLICATION SITUATION

Cracks were injected and pinned before a two wrap system was applied.

APPLICATION METHOD

Done by hand .

BELZONA FACTS

Belzona was the preferred way to repair this concrete pedestal

INDUSTRY

Power

LOCATION

oklahoma City

APPLICATION DATE

March 2024

PRODUCTS

Belzona 1982 (SuperWrap II)
Belzona SuperWrap

SUBSTRATE

Concrete

PHOTOS

1. Power plant water cooling pipe pedestal and crack
2. Superwrap II starting being applied
3. Second wrap on pedestal
4. Final picture with consolidation tape

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

