

REPAIR OF HOLED NOZZLES ON A VESSEL

ID: 9390



PROBLEM

Customer had a process vessel containing a dangerous chemical during process which has faced severe corrosion at the nozzle joints.

APPLICATION SITUATION

Due to the position/placement and time restrictions, the customer was unable to remove and or replace the vessel which would have equated to over AUD 200,000 in total costing. Instead, Belzona solution was offered to save the customer a considerable amount of money at a far cheaper cost allowing for continued production.

APPLICATION METHOD

Repair area, which was originally coated and corroded was ground and clean back to bare metal exposed the hole on the tank/nozzle. Belzona 1212 was the product selected to bond and repair the area, due to inability to carry out any form of abrasive blasting.

Using reinforcement mesh and a metal mesh to cover the hole, the Belzona 1212 was applied in conjunction.

Once cured, Belzona 5831 was applied to coat the repair area.

BELZONA FACTS

By using Belzona products, the immediate need to shut the vessel down was eliminated, allowing it to be placed back in service at a significant cost savings against replacement. Approximately AUD 190,000 in savings.

INDUSTRY

Chemical & Petrochemical

LOCATION

Melbourne, Australia

APPLICATION DATE

October 2023

PRODUCTS

Belzona 1212
Belzona 5831 (ST-Barrier)
Accessories

SUBSTRATE

Carbon steel

PHOTOS

1. Severe through wall corrosion at the base of the nozzles exposed dangerous chemicals during the process
2. Mixing Belzona 1212 in preparation for the repair
3. Application of Belzona 1212 over repair area with reinforcement plate/mesh to be fitted
4. Completion of the application coated with Belzona 5831

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

