

BELZONA 4311 ON CHEMICAL CONTAINMENT AREA

ID: 9399



PROBLEM

The customer did not really have a problem with the concrete but decided to protect the containment area avoiding futures damages of chemical attack.

APPLICATION SITUATION

The floor was hand propped with angel grinders and diamond tip blades. After that it was cleaned and a first back coat was applied of Belzona 5811. After it was cured a two coat system was applied of Belzona 4311 gray and red.

APPLICATION METHOD

Hand tools and brush applied

BELZONA FACTS

The customer has used this protection/solution in many facilities and wanted the same application in this new location.

INDUSTRY

Power

LOCATION

Oklahoma

APPLICATION DATE

May 2024

PRODUCTS

Belzona 4311 (Magma CR1)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. Beginning of the application
2. Application of first coat of Belzona 4311 gray
3. Application of second coat of Belzona 4311 red
4. Application complete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

