

CONCRETE FLOOR REPAIRS

ID: 9406



PROBLEM

The customer was experiencing that their steel wheel conveyor system due to heavy loads were wearing grooves into the concrete floor.

APPLICATION SITUATION

Concrete floor at the moving conveyor production area was in need of repairs and the customer was in need of a quick fix.

APPLICATION METHOD

Application was carried out using the Belzona System Leaflet FPA-1

BELZONA FACTS

The Belzona customer is very pleased with the results of the products used, they are scheduling to repair more floor areas at the next plant shutdown.

INDUSTRY

General Industry

LOCATION

Southwestern Ontario

APPLICATION DATE

April 2023

PRODUCTS

Belzona 4111 (Magma-Quartz)

Belzona 4911 (Magma TX Conditioner)

Belzona 9111 (Cleaner Degreaser)

SUBSTRATE

Concrete

PHOTOS

1. Floor area showing where the grooves have been repaired on this conveyor.
2. Floor area showing where the grooves have been repaired on this conveyor.
3. Floor area showing where the grooves have been repaired on this conveyor.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

