

BELZONA PROTECTS GRP WATER TANKS

ID: 9414



PROBLEM

Two GRP cold water storage tanks were in need of relining to protect the substrate & bring up the hygiene standards of the tanks.

APPLICATION SITUATION

Removal of the tanks was impossible to remove due to the location within the building. The only option was renewing the condition of the tanks in place.

APPLICATION METHOD

The tanks were grit blasted to clean & prepare the GRP substrate. Two coats of Belzona 5811 DW2 were then applied.

BELZONA FACTS

The tanks were completed in two weeks with minimal disruption to the operations within the building.

INDUSTRY

Local Authorities & Municipalities

LOCATION

Scotland

APPLICATION DATE

June 2016

PRODUCTS

Belzona 5811DW (DW Immersion Grade)

SUBSTRATE

GFRP

PHOTOS

1. Before internal
2. Complex geometry
3. During inspection
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

