

BELZONA STEP NOSING REPAIR

ID: 942



PROBLEM

Porters had been bouncing beer barrels down the steps from the bar situated on the floor above. This was damaging the concrete step nosings.

APPLICATION SITUATION

Damaged step nosings.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & -8.

BELZONA FACTS

Belzona was chosen due to its high bond strength, impact resistance and hard wearing non-slip surface proven in similar environments.

INDUSTRY

Buildings & Structures

LOCATION

Racecourse, Liverpool, England

APPLICATION DATE

March 2007

PRODUCTS

Belzona 4111 (Magma Quartz) Belzona 4411 (Granogrip)

SUBSTRATE

Concrete

PHOTOS

1. Steps showing signs of damage
2. Close up of damage
3. Steps repaired
4. Close up of repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

