

BADLY DETERIORATED PROCESS TANK DUE TO EROSION CORROSION AND HIGH ALKALINITY REFURBISHED BY BELZONA.

ID: 9425



PROBLEM

Process tank was in a deplorable state after years of wear due to erosion corrosion.

APPLICATION SITUATION

Customer decided to refurbish with Belzona to give protection which would be the same approach if a new tank is purchased.

APPLICATION METHOD

- Tank was cleaned using a power tool and a cleaner/ degreaser.
- Internal of the tank was rebuild with Belzona 1121.
- The worn part at the top was reinforced with Belzona superwrap II.
- The internal was then coated with Belzona 1341 and external with Belzona 5811.

BELZONA FACTS

Belzona was able to bring tank back to life and it was put back to service afterwards.

INDUSTRY

Mining & Quarrying

LOCATION

Ontario, Canada

APPLICATION DATE

May 2024

PRODUCTS

Belzona 1121 (Super XL-Metal)
Belzona 1341 (Supermetalgilde)
Belzona 1982 (SuperWrap II)
Belzona SuperWrap II
Belzona 5811 (Immersion Grade)

SUBSTRATE

Other

PHOTOS

1. Tank before surface preparation.
2. Tank after surface preparation and rebuilding with Belzona 1121.
3. After wrapping top part of tank with superwrap II, the internal is being coated with Belzona 1341.
4. Tank External after coating with Belzona 5811.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

