

TREATMENT OF THE ZINC SLUDGE TANK.

ID: 9430



PROBLEM

Abrasion, corrosion of the zinc sludge sedimentation tank.

APPLICATION SITUATION

The customer has a very good experience with Belzona products in solving corrosion and erosion problems. That was the main reason why he chose the Belzona solution for this problem as well.

APPLICATION METHOD

The inner surface of the tank was blasted, larger irregularities filled with Belzona 1311 and then covered with two layers of Belzona 1341

BELZONA FACTS

Filling the damages with Belzona 1311 and then coating twice with Belzona 1341 was a quick and cost-effective solution for the customer.

INDUSTRY

Steel & Metal Processing

LOCATION

Kosice Slovakia

APPLICATION DATE

July 2016

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1341 (Supermetalglide)

SUBSTRATE

Carbon steel

PHOTOS

1. Damaged tank.
2. Tank after blasting.
3. Application of the first coat of Belzona 1341.
4. Inspection of the coating after the application of the second coat of Belzona 1341.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

