


BELZONA WEATHERPOOFS POROUS STONework

ID: 944



PROBLEM

House had been recently renovated and sand blasted externally. This process removed the weatherproofing properties of the stonework and as a result moisture was penetrating into the house.

APPLICATION SITUATION

House constructed of stone.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet WPA-8.

BELZONA FACTS

Customer did not want a sheen left on the building once coated. Material of choice also had to be microporous.

INDUSTRY

Buildings & Structures

LOCATION

Private House, Manchester, England

APPLICATION DATE

August 2007

PRODUCTS

Belzona 5122 (Clear Cladding Concentrate)

SUBSTRATE

Sandstone

PHOTOS

1. View of property
2. Windows masked up and ready to go
3. Applying Belzona 5122 with spray unit
4. Application close up

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

