


CONCRETE REPAIR IN WASTEWATER CLARIFIER

ID: 9442



PROBLEM

The Clarifier was suffering from damage to the concrete due to the age of the Clarifier and constant water and chemicals. Instead of replacing they chose Belzona. We have completed 4 out of 6.

APPLICATION SITUATION

The only options the plant had was to repair or replace. This is a tourist town was going to be very difficult to replace they would be looking at years of construction. We were able to repair and have them back in service in a few days.

APPLICATION METHOD

Clarifier was pressure washed and any loose concrete was removed Belzona 4131 and conditioner was applied according to IFU.

BELZONA FACTS

The cost to replace would be downtime and \$200,00 or \$300,000 plus. Belzona was the best option. The city was very happy with the outcome and we have been awarded other projects.

INDUSTRY

Water / Wastewater

LOCATION

Tennessee

APPLICATION DATE

September 2022

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Constant water running over the weirs has caused damage to the concrete
2. Damage after it was cleaned.
3. Applying Belzona 4131
4. Before and after.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA