

CHEMICAL CONTAINMENT AREA

ID: 9443



PROBLEM

The customer had a new containment area they needed to protect.

APPLICATION SITUATION

The customer has several other containment areas that were not coated and are suffering from damage due to the harsh chemicals at the plant. After several visits and a lunch and learn they decided. Belzona was a good option to protect the new area.

APPLICATION METHOD

The new concrete was over 30 days old. It was pressure washed and allowed to dry then a grinder was used to give a profile on the concrete, It was cleaned again to remove the dust. Belzona 4911 primer was applied, then Belzona 4311 second coat of Belzona 4311 Grey followed Red.

BELZONA FACTS

The customer realized it was better to protect now than to wait, which would cause downtime with production, time is money

INDUSTRY

Chemical & Petrochemical

LOCATION

GA

APPLICATION DATE

May 2024

PRODUCTS

Belzona 4311 (Magma CR1)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. New uncoated containment area
2. The first coat of Belzona 4311
3. The second coat of Belzona 4311
4. Follow up picture

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

