

BELZONA 1818/1321 ON PAPER MILL PUMP

ID: 9468



PROBLEM

Paper move pump had severe wash out of years of use and needed to be repaired

APPLICATION SITUATION

The pump was blasted and cleaned. After cleaning it was rebuilt with Belzona 1818. First coat of Belzona 1321 was applied and shortly after that second coat of Belzona 1321.

APPLICATION METHOD

The application was completed according to the corresponding Instructions for Use.

BELZONA FACTS

Belzona has repaired a lot of pumps for this client they were trusted to have this pump done quickly and within budget.

INDUSTRY

Pulp & Paper

LOCATION

OKC

APPLICATION DATE

July 2024

PRODUCTS

Belzona 1321 (Ceramic S-Metal)
Belzona 1818

SUBSTRATE

Other

PHOTOS

1. Damaged pump.
2. Pump rebuilt with Belzona 1818.
3. First coating of Belzona 1321.
4. Finished application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

