

BACKFLOW PREVENTER

ID: 9484

2



PROBLEM

The backflow preventer had stopped working properly

APPLICATION SITUATION

The initial cost of a new backflow preventer was \$10K. The repair was made with a total cost of \$2k. This includes parts.

APPLICATION METHOD

The Belzona 1341N was hand brushed into the lining of the valve.

BELZONA FACTS

The task was completed with a savings of \$7K

INDUSTRY

Commercial Facilities

LOCATION

Knoxville Tennessee

APPLICATION DATE

June 2023

PRODUCTS

Belzona 1341N (Supermetalglide)

SUBSTRATE

Cast Iron

PHOTOS

1. This is a pic of the inside of the backflow preventer before
2. This is a pic of the backflow preventor after

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

