

EMPLOYEE WALKWAY

ID: 9486



PROBLEM

The customer had tried 2 other options. They tried staining the concrete without success. They tried a local hardware store product without success. Then called Belzona.

APPLICATION SITUATION

The customer was not happy with the results of the first 2 tries. The Engineering manager was familiar with Belzona but was trying to find a cheaper option.

APPLICATION METHOD

Belzona 5231 was applied in 2 coats with a small amount of 9221. The 5231 was rolled onto the floor. The 9221 was hand sprinkled.

BELZONA FACTS

Belzona was chosen because of the long-term results. Two cheaper options were tried without satisfactory results.

INDUSTRY

General Industry

LOCATION

Clinton Tennessee

APPLICATION DATE

June 2024

PRODUCTS

Belzona 5231 (SG Laminate)

Belzona 9221 (Surefoot Aggregate White)

SUBSTRATE

Concrete

PHOTOS

1. This is the walkway before. It is very worn looking and it's only been down a month.
2. Belzona 5231 and Belzona 9211 applied.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

