

BELZONA 1341 SOLUTION ON BRASS IMPELLER

ID: 9515



PROBLEM

Customer was looking for a protective coating for the impeller. Belzona was required to provide a suitable solution.

APPLICATION SITUATION

Application with Belzona 1341 was completed within a day, reducing downtime.

APPLICATION METHOD

Application of Belzona 1341 was done by hand as per Instructions for Use.

BELZONA FACTS

We completed five additional pumps for this customer, proving Belzona solutions are reliable.

INDUSTRY

Water / Wastewater

LOCATION

Oklahoma City

APPLICATION DATE

August 2024

PRODUCTS

Belzona 1341 (Supermetalgilde)

SUBSTRATE

Bronze

PHOTOS

1. Look at the impeller after surface preparation was completed.
2. Impeller after the 1st coat with Belzona 1341.
3. 2nd coat of Belzona 1341.
4. Final inspection completed.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

