



BELZONA FLOOR REPAIR

ID: 9517



PROBLEM

This floor was extremely slippery and was worn down from years of use

APPLICATION SITUATION

When the floor was done, the floor was grinded and cleaned by hand and then rollers and brushes were used to apply the Belzona product to the floor.

APPLICATION METHOD

4inch grinders
epoxy rollers
brushes
acetone
type and buckets

BELZONA FACTS

This customer has used Belzona 5811 and 4111 for years. All of the applications that has been done is still in service

INDUSTRY

Food & Drink

LOCATION

Oklahoma

APPLICATION DATE

February 2024

PRODUCTS

Belzona 4111 (Magma-Quartz)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. The floor was prepped with hand tools, cleaned and then repaired with Belzona 4111.
2. First coat of Belzona 5811 black on floor for protection
3. Second and final coat of Belzona 5811
4. The floor 2 weeks after Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

