

BELZONA SOLUTION FOR CONTACT COOLERS

ID: 9519



PROBLEM

Customer was seeing significant erosion under contact cooler on bottom of boat.

APPLICATION SITUATION

Customer needed to get this boat back in the water and out of drydock as soon as possible. Instead of replacing metal we applied Belzona 1121 and Belzona 5821 to bottom of boat and customer was in the water the next day, saving money in the process.

APPLICATION METHOD

Pit filling with Belzona 1121 and overcoat with Belzona 5821 to provide corrosion resistance.

BELZONA FACTS

Downtime and cost savings in comparison to other traditional solutions.

INDUSTRY

Marine

LOCATION

Gibson, Louisisana

APPLICATION DATE

May 2024

PRODUCTS

Belzona 1121 (Super XL-Metal)
Belzona 5821

SUBSTRATE

Carbon steel

PHOTOS

1. Before Application
2. Application of Belzona 1121
3. Application of 1st coat of Belzona 5821 in yellow
4. Application of 2nd coat of Belzona 5821 in grey

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

