


BELZONA REPAIRS FORKLIFT LEAK

ID: 9558



PROBLEM

Leak in hydraulic tank of forklift

APPLICATION SITUATION

Leak in forklift hydraulic tank, could not use the equipment

APPLICATION METHOD

Area prepped by hand tools and repaired with belzona 1212 and 9341

BELZONA FACTS

Repair was completed in 3 hours from initial contact. Saved valuable downtime of important equipment

INDUSTRY

Pulp & Paper

LOCATION

Castlegar

APPLICATION DATE

September 2024

PRODUCTS

Belzona 1212

SUBSTRATE

Carbon steel

PHOTOS

1. Prepared area
2. Repaired area

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

