

BELZONA REPAIRS TILE LINING

ID: 9562



PROBLEM

Holes in multiple locations due to missing tiles

APPLICATION SITUATION

Emergency repair of a flat back chip chute elbow. Chips were piling up outside of the equipment causing fire hazard.

APPLICATION METHOD

Surface mechanically prepared with hand tools, tiles bonded and grouted with Belzona

BELZONA FACTS

Job completed in under 6 hours for an emergency repair. Major cost saving from operational standpoint and downtime savings.

INDUSTRY

Pulp & Paper

LOCATION

Castlegar

APPLICATION DATE

September 2024

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

Belzona 1812 (Ceramic Carbide FP)

SUBSTRATE

Carbon steel

PHOTOS

1. One of many holes
2. Holes repaired and tiles installed with grout
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

