

HOLES ON SHIP DECK COVERED WITH BELZONA.

ID: 9565



PROBLEM

Several holes on a ship deck required patching before being sent out to the museum. Customer did not want to bond a plate to entire surface because of cost implications. Belzona 1111 was used to patch the holes individually after required surface cleaning procedure and coated afterwards.

APPLICATION SITUATION

Belzona was a better option in terms of time saving and cost as compared to bonding a plate to the entire deck.

APPLICATION METHOD

Holes on the deck were cleaned using a power tool to the minimum surface preparation requirement. Then Belzona 1111 is mixed and applied on the deck to patch the holes.

BELZONA FACTS

Belzona was a better option in terms of time saving and cost as compared to bonding a plate to the entire deck.

INDUSTRY

Marine

LOCATION

Ontario

APPLICATION DATE

May 2023

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Carbon steel

PHOTOS

- 1. Deck during inspection
- 2. Deck after application of Belzona 1111
- 3. Entire deck after weeks of application,

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

