

PLATE PATCH ON CHIP CHUTE

ID: 9567



PROBLEM

Hole found in chip chute, causing a mess of material on the floor.

APPLICATION SITUATION

Client required immediate assistance with a hole in a chip chute. Using belzona fast curing composites we were able to get them back up and running in as little as 4 hours.

APPLICATION METHOD

Area cleaned and degreased. Surfaces hand tool prepared, cloth and metal patch used with Belzona 1212 for long term protection.

BELZONA FACTS

Fast curing times allowed the client to get operational as soon as 4 hours and back in production

INDUSTRY

Pulp & Paper

LOCATION

Castlegar

APPLICATION DATE

September 2024

PRODUCTS

Belzona 1212

SUBSTRATE

Carbon steel

PHOTOS

1. Hole prepared for repair.
2. Belzona 1212 used to bond plate.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

