

COAL CHUTE LINING

ID: 9569



PROBLEM

The coal utilized in this process was sticking and plugging the chute.

APPLICATION SITUATION

Rope rescue techniques used to safely provide a non stick coating to coal chute. Belzona helped reduce sticking of the product saving thousands in downtime.

APPLICATION METHOD

Area cleaned and product applied following Belzona's system leaflets.

BELZONA FACTS

Belzona was used for its abrasion properties and ease of application especially dangling from ropes.

INDUSTRY

Mining & Quarrying

LOCATION

Sparwood

APPLICATION DATE

August 2024

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. Chute prior to surface preparation.
2. Chute after a thorough cleaning was performed.
3. During application of Belzona 1321.
4. Completed application with Belzona 1321.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

