


BELZONA PROTECTS COAL CHUTE

ID: 9579



PROBLEM

Sticking coal caused downtime and backed up processes.

APPLICATION SITUATION

During a shutdown it was decided to trial Belzona on a chute liner to prevent coal sticking and downtime. Easy mixing and application made quick work of the lining areas.

APPLICATION METHOD

Grit blast was completed, degreased all surfaces and Belzona was applied according to IFU document.

BELZONA FACTS

This application has worked very well that the client is looking to have many other areas coated to prevent downtime and production stoppages.

INDUSTRY

Mining & Quarrying

LOCATION

Sparwood

APPLICATION DATE

August 2024

PRODUCTS

Belzona 1331

SUBSTRATE

Carbon steel

PHOTOS

1. Pieces of chute grit blades in shop
2. Environmental taken for QC documentation.
3. Application in progress
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

