


REDUCING FRICTION IN ZAMBONI

ID: 9581



PROBLEM

High friction on the factory coating on the aluminum floor plate inside zamboni snow/ice storage. Makes it very difficult to empty without setting it to maintenance mode and climbing inside.

APPLICATION SITUATION

Small maintenance crews for these rural arenas means that any time-saving applications are very well received. This was a common request at the Zamboni distributor level, reducing friction on the floor plates.

APPLICATION METHOD

Air sanders, solvent cleanup, and brush application.

BELZONA FACTS

This was not necessarily a cost saving application, more of a high-demand quality of life/work improvement.

INDUSTRY

Local Authorities & Municipalities

LOCATION

New Brunswick

APPLICATION DATE

August 2024

PRODUCTS

Belzona 1341 (Supermetalglide)

SUBSTRATE

Aluminum

PHOTOS

1. Preparing the painted aluminum surface by high grit sanding and removing all loose and overflowing sealant from edges. Taped up the wall a few inches to prevent snow sticking to them as well.
2. Completed surface with Belzona 1341.
3. Completed surface with Belzona 1341.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

