

BELZONA REPLACES TILE LINING

ID: 9583



PROBLEM

Many damaged tiles and holes on cal reject chutes needed to be repaired.

APPLICATION SITUATION

Massive holes and damaged tile lining was found and required repair in a 48 hour period.

APPLICATION METHOD

Area prepped and holes repaired with Belzona 1311.

Belzona 1321 was used to adhere the tiles and Belzona 1812 as a grout.

BELZONA FACTS

Bespoke adhesion was required as well as a non hot work application required. Belzona was an excellent choice. Holes repaired without any welding and the chute repaired in record time.

INDUSTRY

Mining & Quarrying

LOCATION

Sparwood

APPLICATION DATE

June 2024

PRODUCTS

Belzona 1311 (Ceramic R-Metal)

Belzona 1321 (Ceramic S-Metal)

Belzona 1812 (Ceramic Carbide FP)

SUBSTRATE

Carbon steel

PHOTOS

1. As found
2. Holes repaired and ready for tile
3. Tiles and grout completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

